## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,100,280 B2

Page 1 of 1

APPLICATION NO.: 10/785484

**DATED** 

: September 5, 2006

INVENTOR(S)

: Stefan Moller

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5, line 40, reads "exchanger block each" should read -- exchanger block, each --;

Column 7, line 14, reads "of U-shaped" should read -- of the U-shaped --;

Column 7, line 19, reads "of U-shaped" should read -- of the U-shaped --;

Column 8, line 13, reads "bases surfaces" should read -- base surfaces --; and

Column 8, line 31, reads "connection occurs between" should read -- connection

between --

Signed and Sealed this

Fourteenth Day of August, 2007

JON W. DUDAS

Director of the United States Patent and Trademark Office